DRAFTSMAN

PRINTER 1

FIG.1A




FIG.1B

the state of the s thank the bare than the bark thank

sheet 2 of 9




FIG.2

FIG.3

PRINT

**ENGINE** 

45

FIG.4

sheet 5 of 9





FIG.5

<u> 1935-162 16275</u>

sheet 6 of 9




- (1) RECEIVED DATA IS EMPTY
- (2) JOB DATA IS EMPTY
- (3) RECEIVED DATA IS EMPTY
- (4) JOB DATA IS EMPTY

FIG.6

SUBCLASS

sheet 7 of 9



*FIG.* 7

1.... [1].**]**  O.G. FIG.

sheet 8 of 9




FIG.8

sheet 9 of 9




FIG.9B